

Filled out by: G J Demers

Date: 03 / 15 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>NORWICH</b>
Valuation Sheet: <b>V 43 / 6</b>	Valuation Stationing: <b>263 + 49</b>
Mile Post: <b>D 35.98</b>	GPS Coordinates: N: 43 42.746 W: 72 17.545

Crossing Name: RIVER ROAD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 - 543 M

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other CONCRETE

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 136 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

CR

CA

W CR  
053-543M  
U.S. DOT-AAR





ROSSIN

RAILROAD  
CROSSROAD







CROSSING