

Filled out by: G J Demers

Date: 01 / 02 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL B/S</b>	Town: <b>NORWICH</b>
Valuation Sheet: <b>V 43 / 10</b>	Valuation Stationing: <b>403 + 82</b>
Mile Post: <b>D 31.81</b>	GPS Coordinates: N: <b>43 44.993</b> W: <b>72 13.891</b>

Crossing Name: LEATHERWOOD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 -

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 NH      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 1

Remedial Action (if any) \_\_\_\_\_