

Filled out by: G J Demers

Date: 01/02/2010

### Crossing Inspection Form

Railroad: <b>WACR CRL B/S</b>	Town: <b>THETFORD</b>
Valuation Sheet: <b>V 43 / 14</b>	Valuation Stationing: <b>692 + 70</b>
Mile Post: <b>D 27.84</b>	GPS Coordinates: <b>N: 43 47.838</b> <b>W: 72 11.695</b>

Crossing Name: PAVILLION ROAD (SOUTH)

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 - 551E

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100/112 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_