

Filled out by: G J Demers

Date: 01 / 02 / 2010

Crossing Inspection Form

Railroad: WACR CRL E/S	Town: THETFORD
Valuation Sheet: V 43 / 14	Valuation Stationing: 738 + 22
Mile Post: D 26.98	GPS Coordinates: N: 43 48.551 W: 72 11.326

Crossing Name: Pavilion Road (North)

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 053 - 552 L

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 112 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



WACR
053-552L
U.S. DOT-AAR

27

S
1
2







RAILROAD
CROSSING



053-3521





JCT
113

THE PROBLEM
SOLUTION
CONSTRUCTION
SCHEDULE
PLANNING

PAVING

STOP

RAILROAD
CROSSING



053-528