

Filled out by: G J Demers

Date: 01 / 26 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 / 21</b>	Valuation Stationing: <b>11 06 + 01</b>
Mile Post: <b>D 20.04</b>	GPS Coordinates: <b>N: 43 54.024</b> <b>W: 72 09.238</b>

Crossing Name: TRANSFER STATION

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 - 625 H

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 112 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

RAILROAD  
CROSSING

YIELD

MADE IN U.S.A.  
900-625H  
U.S. DEPT. OF TRANSPORTATION





TRANSFER STATION  
OPEN SATURDAY 8:00 AM  
RECYCLING CENTER OF THE STATE OF NEW YORK  
GATE 10 CHECK ONLY



