

Filled out by: G J Demers

Date: 01 / 08 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 / 22</b>	Valuation Stationing: <b>1151 + 50</b>
Mile Post: <b>D 19.15</b>	GPS Coordinates: N: <b>43 54.493</b> W: <b>72 08.431</b>

Crossing Name: BRIDGE STREET

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location:  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 - 563Y

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 112 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_