

Filled out by: G J Demers

Date: 01 / 08 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 / 23</b>	Valuation Stationing: <b>1191 + 04</b>
Mile Post: <b>D 18.42</b>	GPS Coordinates: <b>N: 44 55.035</b> <b>W: 72 07.729</b>

Crossing Name: \_\_\_\_\_

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 112 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







