

Filled out by: G J Demers

Date: 01 / 02 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 / 24</b>	Valuation Stationing: <b>1248 + 54.5</b>
Mile Post: <b>D 17.33</b>	GPS Coordinates: N: 43 55.791 W: 72 07.247

Crossing Name: YOUR FARM

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 -

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type : 112 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

**WARNING**  
STOP LOOK LISTEN  
FOR TRAIN APPROACHING  
PRIVATE FARM CROSSING  
CROSS AT YOUR OWN RISK



YOUR  
FARM



FAMILY  
ALLIANCE

LOCALLY SOWN... ORGANICALLY GROWN





**WARNING**  
STOP LOOK LISTEN  
FOR TRAIN APPROACHING  
PRIVATE FARM CROSSING  
CROSS AT YOUR OWN RISK





