

Filled out by: G J Demers

Date: 01 / 02 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>FAIRLEE</b>
Valuation Sheet: <b>V 43 / 26</b>	Valuation Stationing: <b>1348 + 51</b>
Mile Post: <b>D 15.44</b>	GPS Coordinates: <b>N: 43 57.386</b> <b>W: 72 06.860</b>

Crossing Name: MALLARY ROAD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 - 576A

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 112 RE      Rail Condition  Good  Fair  Poor


Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

RAIL CROSSING  
CROSSROAD

053-576A  
U.S. DOT-RAA







RAILROAD  
CROSSING

933-3744

NEWMONT FARM  
Caldwell Family  
Dairy  
Distinction



NEWMONT FARM  
Glackston Family  
Dairy of Distinction

