

Filled out by: G J Demers

Date: 01 / 03 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL B/S</b>	Town: <b>BRADFORD</b>
Valuation Sheet: <b>V 43 / 29</b>	Valuation Stationing: <b>1506 + 63</b>
Mile Post: <b>D 12.45</b>	GPS Coordinates: N: <b>43 59.950</b> W: <b>72 07.030</b>

Crossing Name: \_\_\_\_\_

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number **053** - \_\_\_\_\_

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type **11 2 RE**      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken **4**

Remedial Action (if any) \_\_\_\_\_







