

Filled out by: G J Demers

Date: 02 / 01 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL E/S</b>	Town: <b>NEWBURY</b>
Valuation Sheet: <b>V 43 / 35</b>	Valuation Stationing: <b>1816 + 34</b>
Mile Post: <b>D 6.58</b>	GPS Coordinates: N: <b>44 04.158</b> W: <b>72 03.317</b>

Crossing Name: HAVERHILL ROAD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 053 - 598A

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 115 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_