

Filled out by: G J Demers

Date: 05 / 15 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>MONTPELIER</u>
Valuation Sheet: Page <u>2</u> of <u>18</u>	Valuation Stationing: <u>47 + 23</u>
Mile Post: M <u>0.89</u>	GPS Coordinates: N: <u>44 15 38</u> W: <u>72 35 08</u>

Crossing Name: BAILEY AVE

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 837-321W

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____