

Filled out by: G J Demers

Date: 05 / 15 / 2014

### Crossing Inspection Form

Railroad: <b>WACR M&amp;BD</b>	Town: <u>MONTPELIER</u>
Valuation Sheet: Page <u>3</u> of <u>18</u>	Valuation Stationing: <u>61 + 59</u>
Mile Post: <u>M 1.16</u>	GPS Coordinates: N: <u>44 15 38</u> W: <u>72 34 47</u>

Crossing Name: TAYLOR STREET

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 837 - 322 D

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 108      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_









P  
PARKING

NO PARKING  
ANY SIDE  
OF STREET

NO  
HANDICAPPED  
ZONE

NO  
SIDEWALKS

