

Filled out by: G J Demers

Date: 05 / 28 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>MONTPELIER</u>
Valuation Sheet: Page <u>5</u> of <u>18</u>	Valuation Stationing: <u>131 + 36</u>
Mile Post: M <u>2.48</u>	GPS Coordinates: N: <u>44 14 59</u> W: <u>72 33 30</u>

Crossing Name: PIONEER STREET

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 037-327 M

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 115 R Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



RAILROAD
CROSSING

DO NOT
BLOCK
TRACKS

WARNING
ACTIVE BARBICORD
INCREASED
PAVING
EFFECTIVE April 1, 2018

ROAD
CLOSED
500 FT

Denis, Ricker & Brown
INSURANCE
HOME • AUTO • BUSINESS

Denis, Ricker

X

POWELL

SPEED
ZONE
AHEAD





MONTPELIER STOVE WORKS

STOP
HERE ON
RED

DO NOT
BLOCK
DRIVE

NO
PARKING
ON
RED



V.F.W.
POST 292

clothes shoes