

Filled out by: G J Demers

Date: 05/29/2014

### Crossing Inspection Form

Railroad: <b>WACR M&amp;BD</b>	Town: <b>MONTBELIER</b>
Valuation Sheet: Page <b>6</b> of <b>18</b>	Valuation Stationing: <b>162+52</b>
Mile Post: <b>M 3.08</b>	GPS Coordinates: N: <b>44 14 47</b> W: <b>72 32 59</b>

Crossing Name: (AT ROTARY)

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number \_\_\_\_\_

Signaled  Yes  No <sup>WITH GATES</sup> Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 115 RE Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







RAILROAD  
CROSSING

DO NOT  
STOP  
ON  
TRACKS

YIELD



FORMULA



WEST  
2

