

Filled out by: G J Demers

Date: 06/16/2014

### Crossing Inspection Form

Railroad: MBL <u>WACC</u>	Town: <u>BERLIN</u>
Valuation Sheet: <u>8 of 18</u>	Valuation Stationing: <u>254 + 95</u>
Mile Post: <u>M 4.83</u>	GPS Coordinates: N: <u>44 13 21</u> W: <u>72 32 53</u>

Crossing Name: US 302

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 837-334X

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 85      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

HARREY'S PHARMACY



Computer  
REPAIR SERVICE  
2 OR THER MORN



RAILROAD  
CROSSING



RUBBER  
BUBBLES  
Balloons & Party Sup







TER BARN VT

RUBBER BUBBLES

RUBBER BUBBLES

COU

