

Filled out by: G J Demers

Date: 06 / 02 / 2014

### Crossing Inspection Form

Railroad: <b>WACR M&amp;BD</b>	Town: <b>MONTPELIER</b>
Valuation Sheet: Page <b>7</b> of <b>18</b>	Valuation Stationing: <b>17 + 89</b>
Mile Post: <b>Y 0.34</b>	GPS Coordinates: N: <b>44 14 33</b> W: <b>72 32 38</b>

Crossing Name: GAUSSON HILL COMMERCIAL PARK

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 037-335E

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 85      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







