

Filled out by: G J Demers

Date: 06 / 19 / 2014

### Crossing Inspection Form

Railroad: <b>WACR M&amp;BD</b>	Town: <u>BERLIN</u>
Valuation Sheet: Page <u>9</u> of <u>18</u>	Valuation Stationing: <u>293 + 30</u>
Mile Post: <b>M</b> <u>5.57</u>	GPS Coordinates: N: <u>44 12 58</u> W: <u>72 32 15</u>

Crossing Name: ROUND TOWER PARK

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 837-3362

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 85      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken \_\_\_\_\_

Remedial Action (if any) BRUSH SHOULD BE CUT ON NW CORNER





RAILROAD  
CROSSING  
C. ROAD

Person in high-visibility vest and cap standing on the right side of the road.



