

Filled out by: G J Demers

Date: 06 / 19 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BERLIN</u>
Valuation Sheet: Page <u>9</u> of <u>18</u>	Valuation Stationing: <u>293 + 30</u>
Mile Post: M <u>5.57</u>	GPS Coordinates: N: <u>44 12 58</u> W: <u>72 32 15</u>

Crossing Name: ROUND TOWER PARK

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 837-3362

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 85 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken _____

Remedial Action (if any) BRUSH SHOULD BE CUT ON NW CORNER