

Filled out by: G J Demers

Date: 06 / 24 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRE</u>
Valuation Sheet: Page <u>11</u> of <u>18</u>	Valuation Stationing: <u>372+ 58</u>
Mile Post: <u>M 7.05</u>	GPS Coordinates: N: <u>44 12 22</u> W: <u>72 30 46</u>

Crossing Name: BERLIN STREET

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 037-342P

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 115 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







Worker in a yellow safety vest and blue pants standing on the left side of the road.

SPEED
LIMIT
25

