

Filled out by: G J Demers

Date: 06 / 24 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRE</u>
Valuation Sheet: Page <u>11</u> of <u>18</u>	Valuation Stationing: <u>377 + 40</u>
Mile Post: <u>M 7.14</u>	GPS Coordinates: N: <u>44 12 20</u> W: <u>72 30 40</u>

Crossing Name: TENCO INDUSTRIES (HILL-MARTIN)

Type: Public Private Farm Other _____

Location: Main Track Siding Spur Yard Other _____

AAR DOT Number _____

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 80 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____