

Filled out by: G J Demers

Date: 07 / 11 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRE</u>
Valuation Sheet: Page <u>13</u> of <u>18</u>	Valuation Stationing: <u>461 + 51</u>
Mile Post: M <u>8.74</u>	GPS Coordinates: N: <u>44 11 10</u> W: <u>72 29 51</u>

Crossing Name: CIRCLE STREET

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 837-358 L

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 80 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



X

RAILROAD
CROSSING

WARNING
ACTIVE RAILROAD
EXPECT INCREASED
RAIL TRAFFIC
EFFECTIVE JUNE 1, 2010



NOTICE

A person wearing a high-visibility vest and a hard hat stands near the white building on the right side of the tracks.



RAIL CROSSING
CROSSROAD

RAIL CROSSING



Lorenzini's
Automotive
Diagnostic, Service, and Repairs
Foreign and Domestic
622-0845

RAILROAD
CROSSING