

Filled out by: G J Demers

Date: 07/16/2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRE</u>
Valuation Sheet: Page <u>16</u> of <u>18</u>	Valuation Stationing: <u>576 + 43</u>
Mile Post: <u>M 10.92</u>	GPS Coordinates: N: <u>44 10 10</u> W: <u>72 28 56</u>

Crossing Name: CONTI SUES

Type: Public Private Farm Other _____

Location: Main Track Siding Spur Yard Other _____

AAR DOT Number 837-362 B

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 90 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 1

Remedial Action (if any) _____









Filled out by: G J Demers

Date: 07/16/2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BORRE</u>
Valuation Sheet: Page <u>16</u> of <u>18</u>	Valuation Stationing: <u>576 + 43</u>
Mile Post: M <u>10.92</u>	GPS Coordinates: N: <u>44 10 10</u> W: <u>72 28 56</u>

Crossing Name: CONTI FUELS (SIDING)

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 837-362 B

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 80 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







