

Filled out by: G J Demers

Date: 07/16/2014

### Crossing Inspection Form

Railroad: <b>WACR M&amp;BD</b>	Town: <u>BARRE</u>
Valuation Sheet: Page <u>16</u> of <u>18</u>	Valuation Stationing: <u>576 + 43</u>
Mile Post: <u>M 10.92</u>	GPS Coordinates: N: <u>44 10 10</u> W: <u>72 28 56</u>

Crossing Name: CONTI SUES

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location:  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 837-362 B

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 90      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 1

Remedial Action (if any) \_\_\_\_\_