

Filled out by: G J Demers

Date: 03 / 16 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>COVENTRY</b>
Valuation Sheet: <b>V 43 / 98</b>	Valuation Stationing: <b>5159 + 48</b>
Mile Post: <b>L 6.57</b>	GPS Coordinates: N: <b>44 50.593</b> W: <b>72 12.404</b>

Crossing Name: HAMEL ROAD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 871 D

Signalled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_