

Filled out by: G J Demers

Date: 03 / 16 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>COVENTRY</b>
Valuation Sheet: <b>V 43 / 98</b>	Valuation Stationing: <b>5151 + 53</b>
Mile Post: <b>L 6.62</b>	GPS Coordinates: N: <b>44 50.549</b> W: <b>72 12.403</b>

Crossing Name: HOWSE ROAD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - B72K

Signalled  Yes  No Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 1

Remedial Action (if any) \_\_\_\_\_



WACR  
850-872K  
U.S. DOT-AAR









