

Filled out by: G J Demers

Date: 03/16/2010

### Crossing Inspection Form

|                                      |  |
|--------------------------------------|--|
| Railroad: <b>WACR CRL L/S</b>        | Town: <b>IRASBURG</b>  |
| Valuation Sheet:<br><b>V 43 / 97</b> | Valuation Stationing:<br><b>5099 + 03</b>                      |
| Mile Post:<br><b>L 7.62</b>          | GPS Coordinates:<br>N: <b>44 49.703</b><br>W: <b>72 12.107</b> |

Crossing Name: ROCKY'S

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 875 P

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_