

Filled out by: G J Demers

Date: 03/16/2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: IRASBURG
Valuation Sheet: V 43 / 97	Valuation Stationing: 5096 +80
Mile Post: L 8.03	GPS Coordinates: N: 44 49.364 W: 72 12.203

Crossing Name: LA MONDA

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 877 U

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____