

Filled out by: G J Demers

Date: 03 / 16 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARTON</b>
Valuation Sheet: <b>V 43 / 96</b>	Valuation Stationing: <b>5031 + 50</b>
Mile Post: <b>L 8.91</b>	GPS Coordinates: <b>N: 44 48.645</b> <b>W: 72 12.204</b>

Crossing Name: MAIN STREET

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 879H

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

WILKINSON  
CROSSROAD

WACR  
850-879H  
U.S. DOT-AAR



G S P  
MADE IN CANADA





DO NOT ENTER



collette  
**STOVES  
&  
FIREPLACES**





STOVES & FIREPLACES

NO STOPPING



HT

Thermo Pride  
HEATING COOLING





FAMILY DOLLAR

LAKE REGION  
USED  
APPLANCES  
&  
FURNITURE