

Filled out by: G J Demers

Date: 03/16/2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: BARTON
Valuation Sheet: V 43 / 96	Valuation Stationing: 5025 + 14
Mile Post: L 9.11	GPS Coordinates: N: 44 48.472 W: 72 12.283

Crossing Name: SIDING (RAILROAD AVENUE)

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 882R

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____