

Filled out by: G J Demers

Date: 03/16 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARTON</b>
Valuation Sheet: <b>V 43 / 95</b>	Valuation Stationing: <b>4963 + 26</b>
Mile Post: <b>L 10.17</b>	GPS Coordinates: <b>N: 44 47.599</b> <b>W: 72 12.673</b>

Crossing Name: BOUDREAU LANE

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 885 L

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

CRA  
AD



WACR  
850-885L  
U.S. DOT-AAR









