

Filled out by: G J Demers

Date: 03/16 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARTON</b>
Valuation Sheet: <b>V 43 / 92</b>	Valuation Stationing: <b>4818 + 82</b>
Mile Post: <b>L 12.92</b>	GPS Coordinates: N: <b>44 45.568</b> W: <b>72 11.472</b>

Crossing Name: STEVIE BROWN'S - V.A.S.T.

Type:  Public  Private  Farm  Other SNOWMOBILE TRAIL

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 891 P

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_