

Filled out by: G J Demers

Date: 03 / 16 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARTON</b>
Valuation Sheet: <b>V 43 / 91</b>	Valuation Stationing: <b>4799 + 42</b>
Mile Post: <b>L 13.29</b>	GPS Coordinates: <b>N: 44 45.454</b> <b>W: 72 11.166</b>

Crossing Name: Maple Hill Road

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 892W

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

C R

C A D

WACR  
850-892W  
U.S. DOT-AAR

MADE IN CANADA  
G S P







