

Filled out by: G J Demers

Date: 03 / 16 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: BARTON
Valuation Sheet: V 43 / 91	Valuation Stationing: 4799 + 42
Mile Post: L 13.29	GPS Coordinates: N: 44 45.454 W: 72 11.166

Crossing Name: Maple Hill Road

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 892W

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____