

Filled out by: G J Demers

Date: 01 / 19 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: BARTON
Valuation Sheet: V 43 / 85	Valuation Stationing: 4472 + 52
Mile Post: L 19.37	GPS Coordinates: N: 44 42.003 W: 72 05.582

Crossing Name: DREW ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 904N

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



WACR
850-904N
U.S. DOT-AAR







