Filled out by: G J Demers

Date: 03 / 30 / 2010

Crossing Inspection Form

Railroad: **WACR CRL L/S**	Town: **SUTTON**
Valuation Sheet: **V 43 /** 80	Valuation Stationing: 4203 + 24
Mile Post: **L** 24.58	GPS Coordinates: N: 44 39. 29 W: 72 01. 11

Crossing Name: SUTTON ROAD

Type: ☒ Public ☐ Private ☐ Farm ☐ Other _____

Location ☒ Main Track ☐ Siding ☐ Spur ☐ Yard ☐ Other _____

AAR DOT Number **850 -** 908 R

Signaled ☐ Yes ☒ No Crossbucks ☒ Yes ☐ No

Road Surface ☐ Paved ☐ Concrete ☐ Rubber Panels ☒ Gravel ☐ Planks

Flangeway ☐ Rubber ☒ Rail ☐ Plank ☐ Wheel cut ☐ Other _____

Overall crossing condition ☐ Good ☒ Fair ☐ Poor

Rail Size / Type **100 REHF** Rail Condition ☒ Good ☐ Fair ☐ Poor

Line of Sight ☒ Good ☐ Fair ☐ Poor

Number of Photos Taken 4

Remedial Action (if any) _____