

Filled out by: G J Demers

Date: 05 / 24 / 2010

Crossing Inspection Form

| | |
|--------------------------------------|--|
| Railroad: WACR CRL L/S | Town: SUTTON |
| Valuation Sheet: V 43 / 79 | Valuation Stationing: 4139 +08 |
| Mile Post: L 25.80 | GPS Coordinates: N: 44 38. 45 W: 78 00. 08 |

Crossing Name: TARA LYNN'S

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 909 X

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

050 909 X





RAILROAD
CROSSING

CR... ROAD

11.25



