

Filled out by: G J Demers

Date: 04/23/2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>SUTTON</b>
Valuation Sheet: <b>V 43 / 78</b>	Valuation Stationing: <b>4117 + 30</b>
Mile Post: <b>L 26.21</b>	GPS Coordinates: <b>N: 44 38.575</b> <b>W: 72 59.670</b>

Crossing Name: \_\_\_\_\_

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - xxx S

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_