

Filled out by: G J Demers

Date: 01 / 18 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: BURKE
Valuation Sheet: V 43 / 78	Valuation Stationing: 4077 + 36
Mile Post: L 26.95	GPS Coordinates: N: 44 38.294 W: 71 58.878

Crossing Name: Burke Hill Road

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 912F

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

RAILROAD
CROSSROAD

WACR
850-912F
U.S. DOT-AAR









