

Filled out by: G J Demers

Date: 01 / 18 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: BURKE
Valuation Sheet: V 43 / 77	Valuation Stationing: 40 30 + 50
Mile Post: L 27.85	GPS Coordinates: N: 44 37.716 W: 71 58.194

Crossing Name: HAYDEN CROSSING

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 914 U

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

CROSSROAD

WACR
850-914U
U.S. DOT-AAR

MADE IN CANADA

27.85

850 914 U









