

Filled out by: G J Demers

Date: 01 / 18 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: LYNDON
Valuation Sheet: V 43 / 71	Valuation Stationing: 3725 + 17
Mile Post: L 33.64	GPS Coordinates: N: 44 32.962 W: 71 59.660

Crossing Name: VT ROUTE 114

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 916 H

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

CROSSROAD

WACR
850-916H
U.S. DOT-AAR

MADE IN CANADA









