

Filled out by: G J Demers

Date: 04 / 19 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: LYNDON
Valuation Sheet: V 43 / 70	Valuation Stationing: 3655 + 69
Mile Post: L 34.96	GPS Coordinates: N: 44 31.892 W: 72 00.146

Crossing Name: US 5

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 919 D

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

CROSSROAD

WACR
850-919D
U.S. DOT-AAR

Safetran Systems Corp.



RAILROAD
CROSSING
CR 2 ROAD







RAILROAD
CROSSING

RAILROAD
CROSSING
35

