

Filled out by: G J Demers

Date: 04 / 19 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>LYNDON</b>
Valuation Sheet: <b>V 43 / 69</b>	Valuation Stationing: <b>3612 + 20</b>
Mile Post: <b>L 35 .78</b>	GPS Coordinates: <b>N: 44 31.174</b> <b>W: 72 00.126</b>

Crossing Name: US 5

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 920X

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 115 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

WAER  
850-920X  
U.S. DOT-AAR

RACO  
MINNEAPOLIS

L 35.76  
850 920 X

VERMONT  
RAIL  
SYSTEM





Lyndonville  
**AGWAY**

GROW WITH US

PET SUPPLIES

DOGIE DAY CAMP  
LAWN & GARDEN







GREEN



WHITE HOLE PLAZA  
WALMART  
PZA