

Filled out by: G J Demers

Date: 04/21/2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: LYNDON
Valuation Sheet: V 43 / 68	Valuation Stationing: 3582 + 38
Mile Post: L 36.34	GPS Coordinates: N: 44 30.774 W: 71 59.755

Crossing Name: DODGE / GIDLOW

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - xxx E

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



850

IVE

U.S. DEPT. OF...







