

Filled out by: G J Demers

Date: 04 / 06 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>St. JOHNSBURY</b>
Valuation Sheet: <b>V 43 / 67</b>	Valuation Stationing: <b>3499 + 55</b>
Mile Post: <b>L 37.92</b>	GPS Coordinates: <b>N: 44 29.600</b> <b>W: 72 00.287</b>

Crossing Name: KILN

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location:  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 924A

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_



FOR SALE  
REASONABLE  
TERMS  
CALL





LOADING /  
UNLOADING  
INSTRUCTIONS  
SAFETY IN  
STRUCTIONS  
WARNING  
DO NOT  
STEP ON  
THIS  
EQUIPMENT  
KEYBOARD



