

Filled out by: G J Demers

Date: 01 / 15 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>St. JOHNSBURY</b>
Valuation Sheet: <b>V 43 / 62</b>	Valuation Stationing: <b>32.52 + 47</b>
Mile Post: <b>L 42.59</b>	GPS Coordinates: N: 44 25.761 W: 72 01.053

Crossing Name: QUEST

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 850 - 936 U

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_