

Filled out by: G J Demers

Date: 01 / 15 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: St. JOHNSBURY
Valuation Sheet: V 43 / 62	Valuation Stationing: 3244 + 52
Mile Post: L 42.74	GPS Coordinates: N: 44 25 . 40 W: 72 00 . 57

Crossing Name: TIMSON

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 850 - 937B

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



950 937

880

4

8

7



RAILROAD STREET
APARTMENTS
185 - 187 - 189





TBSI
TIMSON'S
BUILDING & SIDING, INC.

paradigm



