

Filled out by: **G J Demers**

Date / Time: 10/02/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>RUTLAND</u>
Valuation Sheet: V3/52	Valuation Stationing: <u>2694+63</u>
Mile Post: B 51.03	GPS Coordinates: N: <u>43.58924</u> W: <u>72.96269</u>

Crossing Name: COLD RIVER ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 051 283 Y

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



Ste Corp.



RAIL
CROSSING

RAIL
CROSSING

Miller Pl

Sto
Corp. →



RAILROAD
CROSSING



