

Filled out by: **G J Demers**

Date / Time: 10/02/13

**Crossing Inspection Form**

Railroad: <b>GMRC</b>	Town: <u>RUTLAND</u>
Valuation Sheet: <b>V 3 / 52</b>	Valuation Stationing: <u>2706 + 67</u>
Mile Post: <b>B 51.26</b>	GPS Coordinates: N: <u>43.59221</u> W: <u>72.96453</u>

Crossing Name: CURTIS AVENUE

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 851 284F

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 105      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor AT NORTH WEST CORNER

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







RAILROAD  
CROSSING

RAILROAD  
CROSSING  
2  
TRACKS

