

Filled out by: **G J Demers**

Date / Time: 10/03/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>ROTLAND</u>
Valuation Sheet: V 3 / 52	Valuation Stationing: <u>2729+80</u>
Mile Post: B 51.69	GPS Coordinates: N: <u>43.59714</u> W: <u>72.97015</u>

Crossing Name: US ROUTE 7

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 851 286 U

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 115 Rail Condition Good Fair Poor SPERRY
ROIL

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







AUBUCHON
REALTY

RETAIL SPACE
AVAILABLE
1900 - 2675 SQ FT
802-773-3225

CALL US OR
VISIT OUR WEBSITE
WWW.AUBUCHONREALTY.COM

RENTAL
3600

